

**Fast & Reliable PHE Solutions**

# 7 Days EX-Work



## Why wait weeks when Hisaka can deliver in just 7 days!



**Urgent order?**

We've delivered in less than 24 hours!

Long lead times cause:

- Delays
- Production Stoppages
- Lost Revenue

Hisaka ensures PHE are ready to ship within 7 working days (Ex-Works Malaysia)

## The Advantages



**Faster Delivery**

7-day EX-Work lead time on select models



**Guaranteed Stock**

Priority inventory for fast fulfillment



**Minimized Downtime**

Keep operations running smoothly



**Proven Track Record**

Proven success in the region



誠心

“Delivering Sincerity and Creativity”

# Available Models & Specifications



Scan For Full Catalog

	LX-00	UX-10	LX-10	RX-10	LX-30	RX-30
<b>Connection Diameter</b>	2"	2"	4"	4"	6"	6"
<b>Max. Flow rate/unit</b>	69 m <sup>3</sup> /h	97 m <sup>3</sup> /h	197 m <sup>3</sup> /h	197 m <sup>3</sup> /h	481 m <sup>3</sup> /h	455 m <sup>3</sup> /h
<b>Max. Working Pressure</b>	1.88 MPaG	1.69 MPaG	1.76 MPaG	1.69 MPaG	1.23 MPaG	1.23 MPaG
<b>Max. Working Temperature</b>	180 °C	150 °C	180 °C	180 °C	180 °C	180 °C
<b>Max. Heat Transfer area/unit</b>	5 m <sup>2</sup>	30 m <sup>2</sup>	15 m <sup>2</sup>	30 m <sup>2</sup>	100 m <sup>2</sup>	200 m <sup>2</sup>

\*\*Max working pressure is based on Manufacturer Standard.

## Who Benefits From This Solution?



**Manufacturers & Plants**  
Requiring rapid PHE replacements



**Operators & Maintenance Teams**  
Minimizing downtime



**Procurement Teams**  
Seeking fast, reliable solutions



## How To Get Started?

1

Check models & specs




2

Contact our sales team



3

Get your PHE in 7 days



# Contact Us Today!

+603 8081 4185    [heatexc@hisaka-asia.com](mailto:heatexc@hisaka-asia.com)    [www.hisaka-asia.com](http://www.hisaka-asia.com)

Scan to find out more



T&C Apply.